

Fokker F50 (F27 Mk 50) Series Aeroplanes

**AD/F50/14
Amdt 1**

Outer Wing End Rib Access Panel

6/89

Applicability: S/No. 20103 to 20108 and 20110 to 20145 inclusive.

Requirement: Action in accordance with Fokker SB F50-57-004. Rev. 1.

Note: RLD AD 89-017 Issue 2 refers.

Compliance: Prior to 31 May 1989.

Background: Deformation of the access panel increases the possibility of ice accretion and can cause heavy operation of the aileron during icing conditions. Amendment 1 references Revision 1 to the Requirement Document which lists additional aircraft affected, none of which are presently on the Australian Register.