

**State of Israel
Ministry of Transport
Civil Aviation Authority**

**AD No. 25-04-05-09R1
Date: November 12, 2008**

AIRWORTHINESS DIRECTIVE

This Airworthiness Directive, issued by the Civil Aviation Authority in accordance with the Israeli Aviation Regulations, applies to an aircraft for which our records list you as the registered owner. It affects aviation safety and requires your immediate attention. No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with that Directive.

APPLIES TO: Gulfstream Aerospace LP (GALP) Model **G150** aircraft, serial numbers **201** through **233**, certificated in any category.

SUBJECT: Replacement of baggage compartment rubber seals manufactured by Gumiyan with seals manufactured by Rubbercraft.
Revision 1 of this AD supersedes the original issue and includes the following changes:

1. "Emergency" was deleted from the title due to typographical error.
2. Compliance time was changed from 6 months to 12 months.
3. Effective date was changed.

REASON: IAI Company Flammability tests revealed that the baggage compartment rubber seals manufactured by Gumiyan are not compliant with FAR 25, Appendix F, Part I requirements.

ACTION: Unless previously accomplished, replace the baggage compartment rubber seals manufactured by Gumiyan with seals manufactured by Rubbercraft per Gulfstream Service Bulletin No. 150-25-055 dated October 28, 2008.

COMPLIANCE: Compliance is required within 12 months after the effective date of this AD.

EFFECTIVE DATE: November 12, 2008.

FOR FURTHER INFORMATION CONTACT: Mr. Boris Levin, Engineering Branch, CAAI - P.O.Box 8, Ben-Gurion Airport, Israel 70100.
Telephone: 972-3-9774-541, Fax: 972-3-9774592, e-mail levinb@mot.gov.il