
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, this AD is revoked by CASA ADCX 005/10

British Aerospace BAe 125 Series Aeroplanes

AD/HS 125/8 Engine Mounting Beam - Modification 7/2010

Requirement: CANCELLED.

This AD is cancelled on 22 April 2010.

Background: This AD was raised in 1967 against Hawker Siddeley Aviation Service Bulletin (SB) 125-53-22 requiring a modification to protect the engine mounting beam from damage and corrosion during service. Compliance was required within 500 hours TIS.

As this AD has been promulgated for an extended period it is considered no longer required. This AD is therefore cancelled.