
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, this AD is revoked by CASA ADCX 007/10.

British Aerospace BAe 125 Series Aeroplanes

AD/HS 125/9 Fuel Filter De-icing System - Inspection 8/2010
Amdt 2

Requirement: CANCELLED.

This AD is cancelled on 22 April 2010.

Background: This AD was first raised in 1967 and amended in 1968 requiring repetitive tests and inspections for fuel or methanol leaks from fuel filter and windshield de-icing systems in accordance with Hawker Siddeley Aviation Service Bulletin (SB) 125-28-23 and 23A. The AD was again amended in 1973 against Hawker Siddeley Aviation Service Bulletin (SB) 125-28-56 enabling a modification to be incorporated to terminate the need for repetitive inspections.

As this AD has been promulgated for an extended period giving plenty of time for the modification to be incorporated, it is considered that this AD it is no longer required. This AD is therefore cancelled.