

British Aerospace BAe 125 Series Aeroplanes

AD/HS 125/55 Fuel Filler Neck Flap Valve - Installation 7/81

Applicability: As detailed in the requirement document.

Document: British Aerospace 125 SB No. 28-60-(2465), Rev. No. 2.

Compliance: Before 31 January 1982.

Background: A rubber flap valve is fitted to each of the fuel tank filler necks to minimise the inflight effects of an improperly closed fuel filler cap.