

British Aerospace BAe 125 Series Aeroplanes

AD/HS 125/61

Electrical Power - Modification

5/83

Applicability: All models.

Requirement: British Aerospace 125 Service Bulletin 24-239-(2885).

Compliance: Within 100 hours time in service after 31 May 1983.

Background: To ensure that resetting a circuit breaker onto a system fault will not result in rupture of the 'PE' busbar feeder fuses.