

British Aerospace BAe 125 Series Aeroplanes

AD/HS 125/65

**Main Landing Gear Jack
Attachment Bracket - Inspection**

7/84

Applicability: All models HS/DH/BH 125 incorporating long range fuel tank (modification 255640).

Document: British Aerospace 125 Service Bulletin 32-200.

Compliance: (a) For aircraft with more than 3000 landings as at 31 July 1984 - not later than 30 September 1984.
(b) For aircraft with less than 3000 landings - before exceeding 3000 landings.

Background: Cracking of jack attachment brackets and adjacent door structure has been reported on overseas aircraft. Such cracking could affect opening of the main landing gear doors, thus preventing the gear from lowering.