
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, this AD is revoked by CASA ADCX 003/10.

British Aerospace BAe 125 Series Aeroplanes

AD/HS 125/121
Amdt 1

Fuel Feed Pipe Joints

6/2010

Requirement: CANCELLED.

This AD is cancelled on 22 April 2010.

Background: This AD was raised in 1991, and amended in 1998 against British Aerospace Service Bulletins (SB) 28-86 and 28-87 requiring corrective action to unacceptably misaligned fuel pipe joint couplings. Extreme circumstances could lead to fuel leaks. Compliance with SB 28-86 was required prior to 31 December 1991 and with SB 28-87 prior to 30 June 1992.

The SBs in this AD were classified as mandatory by CAA (UK), and FAA ADs 92-01-09 and 92-22-04.

As this AD required a one-time modification and has been published for an extended period it is considered to be no longer required. This AD is therefore cancelled.