
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, this AD is revoked by CASA ADCX 002/10

British Aerospace BAe 125 Series Aeroplanes

**AD/HS 125/122
Amdt 1**

Water Tank Shroud Outlet

5/2010

Requirement: CANCELLED.

This AD is cancelled on 25 March 2010.

Background: This AD was raised in 1991, re-instated and amended in 1998 against British Aerospace Service Bulletin (SB) 25-67-25A013A requiring a modification to the washbasin water tank by introducing a new collector/outlet and drain pipe below the washbasin water tank outlet to reduce the possibility of aileron control cable icing following washbasin water tank leakage. Compliance was required not later than 31 March 1992.

This AD was made mandatory by CAA (UK) AD 005-07-91 and FAA AD 92-07-03 amendment 39-8199.

As this AD has been published for an extended period and required only a one-time modification, it is considered to be no longer required. This AD is therefore cancelled.