

British Aerospace BAe 125 Series Aeroplanes

AD/HS 125/125

APU Power Supplies

3/92

Applicability: As specified in the requirement document.

Requirement: Action in accordance with BAe Service Bulletin 49-37-25A253A&B.

Note: Action in accordance with this SB is classified mandatory by the UK CAA.

Compliance: Prior to 30 March 1992.

Background: The APU power supply connections are relocated to protect against damage from engine debris.