

British Aerospace BAe 125 Series Aeroplanes

AD/HS 125/131

Hydraulic System Accumulator

12/92

Applicability: All model 125 up to and including the 800 series aircraft.

Requirement: Unless previously carried out, action in accordance with “2. Accomplishment Instructions” contained in Mandatory Service Bulletin No 29-89-3269A.

Note: Compliance with this SB has been classified as Mandatory by the UK CAA.

Compliance: Prior to 31 August 1993.

Background: Due to possible hydraulic fluid contamination of the accumulator air charge, resulting in possible compression ignition, the accumulators are to be charged with nitrogen.