

Israel Aircraft Industries 1123 and 1124 (Westwind) Series Aeroplanes

---

**AD/IAI-W/10**

**Emergency Lighting System**

**8/85**

Applicability: As detailed in Requirement Document.

Requirement: Inspect and Modify the emergency lighting system components according to Accomplishment Instructions Parts 1 and 2 contained in IAI Westwind S.B. 1124-33-010.

Compliance: Within 150 hours time in service after 31 August 1985.

Background: The aircraft manufacturer advises that:

- a) the inertial switch may not be aligned with the longitudinal axis of the aircraft;  
and
- b) the possibility exists for an inadvertent battery pack short circuit to surrounding structure.