

British Aerospace BAe 3100 (Jetstream) Series Aeroplanes

**AD/JETSTREAM/7
Amdt 2**

**Main Landing Gear Hinge Fitting
and Support Angle**

5/95

- Applicability: All Jetstream 3100 series aircraft with constructors numbers 601 to 695 inclusive, without Service Bulletin 57-JM 5218 incorporated.
- Requirement: Inspect in accordance with British Aerospace Service Bulletin (BAe SB) 32-A-JA 850127, Revision 2, dated 11 November 1994.
- Compliance: Initially inspect before exceeding 4000 component landings.
- Re-inspect at the intervals specified in BAe SB 32-A-JA 850127, Revision 2.
- The inspection requirements are unchanged by this Amendment.
- This Amendment is effective from 27 April 1995.
- Background: Cracks have been found at the MLG hinge fittings on the Jetstream fatigue test specimen. In addition, a number of cases of cracks have been reported by operators of earlier series versions of the Jetstream. Amendment 2 redefines the applicability and excludes aircraft incorporating Mod No JM5218 (SB 57-JM 5218 refers).