COMMONWEALTH OF AUSTRALIA CIVIL AVIATION SAFETY AUTHORITY SCHEDULE OF AIRWORTHINESS DIRECTIVES

British Aerospace BAe 3100 (Jetstream) Series Aeroplanes

AD/JETSTREAM/50 Powerplant - Revised Power Lever 12/91 To Manual Fuel Valve

Applicability: All Jetstream 3100 and 3200 Aircraft construction numbers up to and including 928.

Requirement: Action in accordance with the Technical requirements of British Aerospace Service

Bulletin, CAA (UK) mandatory, 71-JM 7755.

Requirement: Prior to 31 March 1992.

Compliance: There have been occurrences of the power lever becoming detached from the manual

fuel valve on the engine. The resulting inability to control the power of the affected

engine required the aircrew to initiate emergency procedures.