

British Aerospace BAe 3100 (Jetstream) Series Aeroplanes

AD/JETSTREAM/52

Escape Hatch Shear Fitting

3/92

- Applicability: Models and Constructor's numbers identified in accordance with the following Accomplishment Instruction Parts of BAe Service Bulletin 52-JM 7752:
- Part A - Jetstream Series 3100 aircraft constructors number 757, and aircraft with constructors numbers in the range 770 to 839 inclusive.
- Jetstream Series 3200 aircraft with constructors numbers in the range 790 to 910 inclusive and 912.
- Part B - Jetstream Series 3200 aircraft with constructors numbers in the range 790 to 910 inclusive and 912.
- Requirement: Action in accordance with Mandatory British Aerospace SB 52-JM 7752.
- Compliance: At the next scheduled 600 hour maintenance check after 6 March 1992 or by 6 July 1992; whichever occurs first.
- Background: During a scheduled inspection on an in-service aircraft, an escape hatch could not be removed without damaging the ceiling trim, due to interference between the shear fitting on the hatch and a furnishing ceiling panel. This interference can prevent removal of the escape hatch in an emergency. The compliance date required by the UK CAA is extended by two months.