

British Aerospace BAe 3100 (Jetstream) Series Aeroplanes

AD/JETSTREAM/59

**Main Wing Lower Skin and
Lower Front Spar Structure**

9/93

Applicability: All Jetstream Series 3100 aircraft.

Requirement: Action in accordance with British Aerospace Jetstream Mandatory Service Bulletin 57-JA 921203.

Note: UK CAA AD 014-05-93 refers.

Compliance: As specified in the Requirement Document, with a completion date of 19 February 1994 for Accomplishment Instructions Parts 1 and 2 of the Requirement Document.

Background: Reports of exfoliation corrosion damage of the lower main skin at bolts which attach the skin to the front spar structure between Stations 36 and 40, LH and RH.