

British Aerospace BAe 3100 (Jetstream) Series Aeroplanes

AD/JETSTREAM/66

**Wing - Main Spar Fuel
Fitting Attachment Holes**

10/94

Applicability: Jetstream 3200 Series aircraft up to and including constructor's number 950.

Requirement: Modify the fuel tank drainage hole at wing station 64.8 on the left and right hand sides in accordance with British Aerospace SB 57-JM 8175 revision 1.

Compliance: Prior to 6000 landings or before 15 March 1995 whichever is the later.

Background: Cracking of the wing main spar webs has been found at this location on the Jetstream 3200 series wing test specimen.