

Gates Learjet 35 and 36 Series Aeroplanes

AD/LEARJET 35/8

**Refrigeration System Condenser
Fan - Inspection and Replacement**

9/78

Applicability: Model 35 with S/Nos. 35-001 to 35-194. Model 36 with S/Nos. 36-001 to 36-040.
And any 35/36 Series Learjet which has had a Condenser Fan changed since 1 July 1977.

Requirement: 1. Inspect the P/No. rubber-stamped on a blade of the refrigeration condenser fan.
2. If the fan bears the P/No. 6608059-3, attach a placard worded as follows to the instrument panel adjacent to the refrigeration system control switch:

WARNING

**DO NOT OPERATE REFRIGERATION SYSTEM UNDER ANY
CIRCUMSTANCES ON THE GROUND OR IN THE AIR UNTIL
FAN HAS BEEN REPLACED.**

Note: The correct fans have blades which taper in thickness towards the tip and bear the P/Nos. 6608059-2 or 6608059-4.

or Gates Learjet SB 35/36-21-3.

Compliance: Before further flight.