

Gates Learjet 35 and 36 Series Aeroplanes

AD/LEARJET 35/9

**Secondary Yaw Damper Servo Cable
Clamp Bolt - Inspection**

12/78

Applicability: All model 35 with S/Nos. 35-001 to 35-182.

All model 36 with S/Nos. 36-001 to 36-038.

Document: Gates Learjet SB 35/36-22-2.

Compliance: Within 100 hours time in service after 31 December 1978.