COMMONWEALTH OF AUSTRALIA CIVIL AVIATION SAFETY AUTHORITY SCHEDULE OF AIRWORTHINESS DIRECTIVES

Gates Learjet 35 and 36 Series Aeroplanes

AD/LEARJET 35/13 Upper Cabin Door Lock 4/80 Mechanism Bolts - Modification

Applicability: All model 35 with S/Nos. 35-001 to 35-274 and 278;

All model 36 with S/Nos. 36-001 to 36-044.

- Requirement: Modify the upper cabin door lock mechanism bolts by installing Gates Learjet Kit No. AMK 79-9.
- Compliance: Within 150 hours time in service after 30 April 1980.
- Background: Modification kit AMK 79-9 provides an additional safety feature to the upper cabin door lock mechanism by installing drilled bolts and lockwiring these bolts in-situ.