

Gates Learjet 35 and 36 Series Aeroplanes

---

**AD/LEARJET 35/20**

**Engine Firewall Sealing**

**8/82**

Applicability: Learjet 35-001 to 35-482; Learjet 36-001 to 36-050.

Document: Gates Learjet Service Bulletin SB35/36-71-2 refers.

Compliance: Within 150 hours after 31 August 1982.

Background: Manufacturers requirement to improve fireproofing at the engine pylon firewall.