
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, this AD is revoked by CASA ADCX 001/10

British Aerospace (Scottish Aviation) Twin Pioneer Series Aeroplanes

AD/SP-TA/2	Hydraulic Valve - Strengthened Gland	4/2010
-------------------	---	---------------

Requirement: CANCELLED.

This AD is cancelled on 29 April 2010.

Background: This Directive raised in 1959 against Scottish Aviation Mod. C285, and made mandatory by CAA (UK) AD 2428 PRE 80, concerned the introduction of steel gland Part # 717924 in lieu of a aluminium gland Part # 717918 in piston-operated shuttle valve Part # 7179. Compliance was before 750 landings and applicable to all series aircraft. Given the extended period that this AD has been published, it is considered to be no longer required. This Directive is therefore cancelled.