

SAAB SF340 Series Aeroplanes

AD/SF340/11

Pitot Systems Water Traps

11/88

Applicability: Model SF340A with serial numbers 004 through 138.

Requirement: Action in accordance with SAAB Scania AB Service Bulletin SF340-34-056 dated 1 August 1988 or later revision.

Note: Swedish Airworthiness Directive No. 1-027 refers.

Compliance: Prior to 31 December 1988.

Background: Water intrusion into the pitot systems may occur in heavy rain. This can result in ice blocking the systems leading to erroneous air data signals.