

SAAB SF340 Series Aeroplanes

---

**AD/SF340/51                      Engine Nacelle Fire Extinguisher Wiring                      3/96**

**Applicability:** This Directive is applicable to Model SF 340A aeroplanes serial numbers SF340-004 through -159 inclusive and Model 340B aeroplanes serial numbers 340B-160 through -345 inclusive.

**Requirement:** Inspect and modify the engine nacelle fire extinguisher wiring in accordance with SAAB Aircraft AB Service Bulletin SAAB 340-26-015 dated 23 November 1995.

*Note: Swedish (LFV) SAD 1-079 refers.*

**Compliance:** No later than the next 4000 flight hour inspection (C check) after 29 February 1996.

**Background:** This Directive supersedes AD/SF340/39. SAAB Aircraft AB have advised that the possibility still exists for incorrect connection of the nacelle fire extinguishers despite incorporation of the modification required by AD/SF340/39. The actions required by this Directive are designed to ensure that the possibility of incorrect installation of fire extinguisher electrical wiring connections is minimised.