

SAAB SF340 Series Aeroplanes

---

**AD/SF340/56**

**Airfoil De-Icing - Introduction of  
New Improved Check Valve**

**2/98**

CANCELLED.

This AD is herewith CANCELLED and superseded by AD/SF340/63.

Background

This Ad was raised against Swedish Airworthiness Directive No.1-107 and SAAB Service Bulletin 340-30-069. Service experience has since proved the measures taken were insufficient to prevent recurrence of the original problem with the check valves. SAAB and the Swedish authority have now issued a new SB and AD to introduce a new check valve to rectify the situation. AD/SF340/63 mandates this action in Australia.