COMMONWEALTH OF AUSTRALIA CIVIL AVIATION SAFETY AUTHORITY SCHEDULE OF AIRWORTHINESS DIRECTIVES

Teledyne Continental Motors Piston Engines

AD/CON/50 Starter Adaptor Shaft Gear P/No 649343 3/88

CANCELLED.

Background: This Directive has been cancelled following advice from the manufacturer of further

starter adaptor shaft failures since the issue of SB M87-13. The manufacturer has issued SB M87-24 which supersedes M87-13. The requirements of SB M87-24 are

reflected in AD/CON/53.