

Lycoming Piston Engines

AD/LYC/45
Amdt 2

Connecting Rod - Inspection

13/92

CANCELLED.

Background: The requirements of this Directive are now reflected in AD/LYC/93.