

Agusta A109 Series Helicopters

AD/A109/22

Sliding Doors Emergency Exit Panel

**8/94
DM**

Applicability: A109A and A109AII.

Requirement: Action in accordance with Agusta Bollettino Tecnico 109-95.

Note: RAI AD 94-71 refers.

Compliance: Part I: Within 25 hours time in service after 26 May 1994.

Part II: At each 100 hour inspection after compliance with Part I.

Part III: Prior to 30 June 1994.

Background: This Directive is issued following the loss of an emergency exit in flight. This was due to incomplete engagement of the locking pins and improper safety wire installation.