

Brantly B-2 Series Helicopters

---

**AD/B-2/28**  
**Amdt 1**

**Tail Rotor Blade Spar - Inspection**

**2/68**

Applicability: All model B2, B2A and B2B.

Document: Brantly SB No. B2B-68-1.

Compliance: At intervals not exceeding 100 hours time in service after 22 February 1968.