
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/BELL 205/17.

Bell Helicopter Textron 205 Series Helicopters

AD/BELL 205/17

**Hydraulic Fluid Temperature
Indicators - Installation**

12/2009

Requirement: CANCELLED.

This AD is cancelled on 19 November 2009.

Background: This unique Australian AD specified once-only action on the dual hydraulic system (if installed) in accordance with SB 205-06-73-1 within 50 hours time in service after January 1974 or at the time of installing a dual hydraulic system. The AD is no longer required.



James Coyne
Delegate of the Civil Aviation Safety Authority

30 September 2009