
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/BELL 205/37.

Bell Helicopter Textron 205 Series Helicopters

AD/BELL 205/37

**Main Rotor Hub Fitting
Assemblies - Inspection**

2/2008

Requirement: CANCELLED.

This AD is cancelled on 14 February 2008.

Background: The Requirement document of this Directive, Bell Service Bulletin 205-77-1, has been removed from the active SB listing published by BHTI. The requirement is now contained in the maintenance manual.



David Villiers
Delegate of the Civil Aviation Safety Authority

19 December 2007