

Bell Helicopter Textron Canada (BHTC) 407 Series Helicopters

AIRWORTHINESS DIRECTIVE

For the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/BELL 407/3.

AD/BELL 407/3

**Thomas Coupling Pack - Cracked
Discs - Inspection**

6/2000

Requirement: CANCELLED.

Background: The Thomas coupling inspection is now contained in the BHTC Maintenance Manual BHT-407-MM-1, Revision 9, Chapter 4, Airworthiness Limitation Schedule.

Transport Canada Airworthiness Directive CF-97-20R1 Refers.



Eugene Paul Holzapfel
Delegate of the Civil Aviation Safety Authority

2 May 2000