

Bell Helicopter Textron 412 Series Helicopters

AD/BELL 412/27

Tailboom Upper Longeron

**12/90
DM**

Applicability: Model 412 with serial numbers:

33001 through 33211

34001 through 34013

36001 through 36013

Requirement: 1. Action in accordance with Part 1 of Bell Alert Service Bulletin No 412-90-49.
2. Action in accordance with Part II of Bell Alert Service Bulletin No 412-90-49.

Compliance: 1. Prior to 30 November 1990.
2. At intervals not exceeding 300 hours time in service after incorporation of Requirement 1.

Background: Incidents of cracked longeron splices have created a requirement for additional access to inspect upper longeron splices, and modification action to increase structural integrity.