

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/HILLER 12/2.

---

### Hiller UH-12 Series Helicopters

**AD/HILLER 12/2**                      **Main Rotor Blade Spar - Inspection**                      **9/2009**

Requirement:    CANCELLED.

This AD is cancelled on 27 August 2009.

Background:     This AD, raised in 1961 against Hiller Service Bulletin (SB) No. 2016, required a modification of the upper and lower blade doublers located adjacent to the blade spar to reduce stress levels in the affected area. Compliance was required before 7 February 1961.

As all affected aircraft would have been modified long ago, this AD is no longer required.



David Villiers  
Delegate of the Civil Aviation Safety Authority

15 July 2009