

Hiller UH-12 Series Helicopters

**AD/HILLER 12/9
Amdt 1**

Horizontal Stabiliser Spar - Inspection

3/78

Applicability: All models UH-12, UH-12A, UH-12B and UH-12C.

Requirement: Remove the horizontal stabiliser, and with the aid of a lens of not less than 8X power, inspect the spar tube for cracking in the vicinity of the stabiliser attachment bolt holes.

Compliance: At intervals not exceeding 300 hours time in service.