

Hiller UH-12 Series Helicopters

AD/HILLER 12/19

Main Rotor Blades - Inspection

11/71

Applicability: All models.

Requirement: 1. Carry out a visual inspection for cracks in the main rotor blades P/No. 53100.

Note: This inspection may be performed and certified by the pilot.

2. Inspect blades P/N 53100 for cracks using an approved dye penetrant method.

Note: Any blades found defective shall be removed from service before further flight.

Compliance: For Para. 1 - Before further flight.

For Para. 2 - Within 10 hours time in service after 16 Nov. 1971.