AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/HU 269/47.

Schweizer (Hughes) 269 Series Helicopters

AD/HU 269/47 Main Rotor Blade Root Fitting Bolts - Main 5/2009 Rotor Blade Damper Bolts - Inspection

Requirement: CANCELLED.

This AD is cancelled on 7 May 2009.

Background: This unique Australian AD was raised in 1974 against Hughes Service Information

Notice (SIN) No. N-119 requiring an inspection to determine if the correct bolts were

installed in the blade root fittings and main rotor blade dampers.

Compliance was: Within 50 hours TIS after 30 August 1974.

This AD has been sufficiently promulgated for the affected aircraft to have been inspected by now; therefore this AD is considered to be no longer required.

James Coyne

Delegate of the Civil Aviation Safety Authority

27 March 2009