

Schweizer (Hughes) 269 Series Helicopters

AD/HU 269/62 Tail Rotor Hub - Inspection and Modification 3/82
Amdt 1

Applicability: All model 269C with S/Nos. 0004 to 0716.

All model 269A, TH-55A, 269A-1 and 269B with LTS tail rotor assembly P/N 269A6034 Series.

All P/N 369A1725 and 369A1725-501 tail rotor hub assemblies.

All P/N 369A1725-5 tail rotor assemblies with S/Nos. 001 to 862.

Document: Hughes SIN No. N-153.1.

Compliance: Within 100 hours time in service after 31 March, 1982.

Background: Manufacturer's SI Notice Revision 1 extends part number effectivity.