

McDonnell Douglas (Hughes) and Kawasaki 369 Series Helicopters

AD/HU 369/17

Tail Rotor Drive System - Inspection

6/75

Applicability: All models equipped with metal tail rotor blades and all models with drive shafts not previously indexed.

Document: Hughes SIN No. HN-86.

Compliance: For Part 1 - Within 100 hours time in service after 30 June 1975.

For Part 2 - At intervals not exceeding 100 hours time in service after 30 June 1975.