

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/HU 369/22 Amdt 1.

---

### McDonnell Douglas (Hughes) and Kawasaki 369 Series Helicopters

**AD/HU 369/22  
Amdt 1**

**Tail Rotor Transmission Attachment  
Bracket Assemblies Inspection**

**5/2009**

Requirement: CANCELLED.

This AD is cancelled on 7 May 2009.

Background: This AD was raised in 1977 against Hughes Service Information Notice (SIN) No. HN-111.1. It required an inspection of the tail rotor transmission attachment bracket assemblies following manufacturer reports of cracks. Compliance was required within 100 hours TIS after 10 November 1977.

As all affected aircraft would have been inspected, and, if necessary, modified long ago, this AD is no longer required.



David Villiers  
Delegate of the Civil Aviation Safety Authority

26 March 2009