
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/HU 369/36.

McDonnell Douglas (Hughes) and Kawasaki 369 Series Helicopters

AD/HU 369/36 Flexible Hose Assembly - Replacement 6/2009

Requirement: CANCELLED.

This AD is cancelled on 4 June 2009.

Background: This unique Australian AD raised in 1979 against Hughes Service Information Notice (SIN) No. DN-34 required a modification to replace the engine oil cooler to engine oil tank return hose with a longer hose assembly to reduce the possibility of vibration induced damage to oil tank or oil cooler assemblies.

Compliance was: As detailed in the requirement document; which was within next 100 hours of helicopter operation after receipt of parts.

This AD has been sufficiently promulgated for the affected aircraft to have been modified by now; therefore this AD is considered to be no longer required.

This AD has been reviewed in accordance with the AD review program. The AD required a modification that has been sufficiently promulgated. This AD is therefore cancelled.



James Coyne
Delegate of the Civil Aviation Safety Authority

24 April 2009