

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/HU 369/52.

---

### McDonnell Douglas (Hughes) and Kawasaki 369 Series Helicopters

**AD/HU 369/52**

**Attachment Hardware for Sta-Strap  
Securing Electric Wiring to Boom  
Fairing at Sta 138.50 - Inspection**

**6/2009**

Requirement: CANCELLED.

This AD is cancelled on 4 June 2009.

Background: This AD, raised in 1981 against Hughes Service Information Notice (SIN) No. DN-96, required a one-time inspection to ensure that a steel washer had not been inadvertently installed under the aluminium rivet securing the sta-strap securing electrical wiring to the boom fairing at STA 138.50. Compliance was required within 100 hours TIS after 31 December 1981.

As all affected aircraft would have been inspected, and, if necessary, modified long ago, this AD is no longer required.



David Villiers  
Delegate of the Civil Aviation Safety Authority

17 April 2009