

Sikorsky S-76 Series Helicopters

AD/S-76/9

**Cyclic Torque Tube - Inspection of
Centre Support Bearing Housing**

3/80

Applicability: Model S-76.

Document: Sikorsky CSB 76-67-7.

Compliance: Within 10 hours time in service after 14 February 1980.

Background: Some bearing support housings have been incorrectly manufactured, with the bearing retaining shoulder on the wrong side. This would permit axial displacement of the bearing along the torque tube.