

Sikorsky S-76 Series Helicopters

AD/S-76/19 Main Rotor Blade - Tip Plate Assembly Retention 6/81
Bolts - Inspection and Replacement

Applicability: All models.

Document: Sikorsky Alert SB 76-65-23.

Compliance: As per requirement document.

Background: The manufacturer has advised the loss of a main rotor blade tip cap in flight.