
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/S-76/37.

Sikorsky S-76 Series Helicopters

AD/S-76/37

**Engine Fire Extinguisher
Harness - Modification**

7/2009

Requirement: CANCELLED.

This AD is cancelled on 2 July 2009.

Background: This unique Australian AD raised in 1985 against Sikorsky Alert Service Bulletin (ASB) 76-26-1 required a modification to fire extinguisher harness P/No 76552-10128-041 and -042 by a wiring change to arrange the dual primers into a parallel configuration to improve system redundancy.

Compliance was: Within 100 hours TIS after 30 April 1985.

This AD has been sufficiently promulgated for the affected seats to have been modified by now; therefore this AD is considered to be no longer required.



James Coyne
Delegate of the Civil Aviation Safety Authority

18 May 2009