

Sikorsky S-76 Series Helicopters

AD/S-76/40

**Power Train Tail Drive Shaft
Bearing Support Assembly**

**9/85
TX**

Applicability: All model S76 which have bearing support assembly bearings manufactured by MRC installed.

Requirement: Action in accordance with Sikorsky Alert Service Bulletin No. 76- 66-20.

Compliance: Before further flight after 31 July 1985.

Background: It has been determined that some bearings manufactured by MRC may have been assembled without grease.