## COMMONWEALTH OF AUSTRALIA CIVIL AVIATION SAFETY AUTHORITY SCHEDULE OF AIRWORTHINESS DIRECTIVES

Eurocopter AS 332 (Super Puma) Series Helicopters

## AD/S-PUMA/14

## **Swashplate Scissors**

10/93 DM

Applicability: All AS 332 C, C1, L and L1 helicopters fitted with swashplate rotating and non-

rotating scissor links P/N 330A31-1407-22 installed with carbide swivel bearings.

Requirement: Action in accordance with Eurocopter Telex Service Nr 10063.S1/0176/93 dated 25

June 93. Telex Service No 01-36 R1 refers.

*Note:* DGAC AD 93-106-050(B) refers.

Compliance: Within 10 hours time in service from 30 July 1993.

Background: The manufacturer has advised that a rotating scissors link suffered an in-flight failure

in the shank bending radius of the swivel bearing.