COMMONWEALTH OF AUSTRALIA CIVIL AVIATION SAFETY AUTHORITY SCHEDULE OF AIRWORTHINESS DIRECTIVES

Allison Turbine Engines - 250 Series

AD/AL 250/5 Amdt 2		Gearbox Assembly - PTO Helica Gearshaft Assembly - Replaceme	
Applicability:	All Model 250-C18, C20, C20B, C20F, B15G, B17, B17B, and B17C, engines with exceptions as listed in the requirement document.		
Requirement:	Allison 250-C18, C18A, C18B, C18C	: CEB-203	Rev. 7
	Allison 250-C20, C20B, C20F	: CEB-1150	Rev. 7
	Allison 250-B15G	: TP CEB-71	Rev. 7
	Allison 250-B17, B17B, B17C	: TP CEB-1126	Rev. 7
Compliance:	In accordance with the Requirement Document Para E.		
Background:	This Directive is amended to reflect the manufacturers Rev. 7 changes to the Requirement Documents Para 1.E Compliance Statement; sub-para 3 which requires the immediate replacement of superseded part numbered PTO shaft in the event of future shockload or sudden stoppage as defined in Para 3.1 and 3.2.		