

Pratt and Whitney Canada Turbine Engines - PT6T Series

AD/PT6T/8

Sundstrand Fuel Pump Drive Wear

6/91

CANCELLED.

Background: The inspection for fuel pump drive shaft wear is now included in the P&WC Maintenance Manual periodic inspection requirements.