



No.	CF-2010-09	1/1
Issue Date	17 March 2010	

AIRWORTHINESS DIRECTIVE

The following airworthiness directive (AD) may be applicable to an aircraft which our records indicate is registered in your name. ADs are issued pursuant to **Canadian Aviation Regulation (CAR) 521 Division X**. Pursuant to **CAR 605.84** and the further details of **CAR Standard 625, Appendix H**, the continuing airworthiness of a Canadian registered aircraft is contingent upon compliance with all applicable ADs. Failure to comply with the requirements of an AD may invalidate the flight authorization of the aircraft. Alternative means of compliance shall be applied for in accordance with **CAR 605.84** and the above-referenced **Standard**.

This AD has been issued by the Continuing Airworthiness Division (AARDG), National Aircraft Certification Branch, Transport Canada, Ottawa, telephone 613 952-4357.

Number: CF-2010-09

Subject: Engine Impeller in-service Life Reduction

Effective: 6 April 2010

Applicability: All Pratt & Whitney Canada (P&WC) PW305A and PW305B engines with impeller part number (P/N) 30B2185 or 30B2486 or 30B2858-01 or 30B4565-01 installation

Compliance: Is required as indicated, unless already accomplished

Background: As a result of a change in the low-cycle fatigue lifing methodology for the IMI 834 material, the recommended service life of certain PW305A and PW305B Impellers has been reduced, as published in the Airworthiness Limitations (AWL) section of Engine Maintenance Manual (EMM).

The in-service life of impellers P/N 30B2185, 30B2486 and 30B2858-01 has been reduced from 12,000 to 7,000 cycles; and of P/N 30B4565-01 from 8,500 to 7,000 cycles.

This Airworthiness Directive (AD) is issued to mandate the incorporation of the revised in-service life limits for the affected impellers, in the AWL section of EMM, as introduced by Temporary Revision (TR) AL-8.

Corrective Actions: Within 30 days from the effective date of this AD, update AWL section of your PW305 EMM P/N 30B1402, to incorporate TR AL-8 for compliance with the revised in-service limits for the affected Impellers, installed on PW305A and PW305B engine.

Authorization: For Minister of Transport, Infrastructure and Communities

ORIGINAL SIGNED BY

Derek Ferguson
Chief, Continuing Airworthiness

Contact: Mr. A K Durrani, Continuing Airworthiness, Ottawa, telephone 613-952-4357, facsimile 613-996-9178 or e-mail CAWWEBFeedback@tc.gc.ca or any Transport Canada Centre.

Pursuant to **CAR 202.51** the registered owner of a Canadian aircraft shall, within seven days, notify the Minister in writing of any change of his or her name or address.

To request a change of address, contact the **Civil Aviation Communications Centre (AARC)** at **Place de Ville, Ottawa, Ontario K1A 0N8**, or **1-800-305-2059**, or www.tc.gc.ca/civilaviation/communications/centre/address.asp

